

Road Safety Audit Feedback Form

Scheme: 12031 Cappagh Road, Galway City

Audit Stage: 1


Route: An Cimín Mór Road

Date of Audit: 10/06/2025

To be Completed by Designer

To Be Completed by Audit Team Leader

Paragraph No. in Safety Audit Report	Problem accepted (yes/no)	Recommended Measures Accepted (yes /no)	Alternative Measures (describe). Give reason for not accepting recommended measure	Alternative Measures or reasons accepted by auditors (yes /no)
2.1	Yes	Yes		
2.2	Yes	Yes		
2.3	Yes	Yes		
2.4	Yes	Yes		
2.5	Yes	No	The swept path analysis has been updated, and vehicles retain within the carriageway'	
2.6	Yes	Yes		
2.7	Yes	Yes		
2.8	Yes	Yes		
2.9	Yes	Yes		
2.10	Yes	Yes		
2.11	Yes	Yes		
2.12	Yes	Yes		

Signed:		Designer	Gift Mzembe	Date:	18/09/2025
Signed:		Client		Date:	21/09/2025
Signed:		Audit Team Leader	Maria Rooney - TOBIN	Date:	